


An aerial photograph of Waterfront Park. The foreground is dominated by a large, calm body of water with a blue-green hue. A stone or concrete seawall runs horizontally across the middle of the frame, separating the water from the park. The park itself is a vast green space with several winding paths. In the upper left, there is a circular area with a yellow, tiered structure, possibly a playground or a small amphitheater. To the right of this, there is a parking lot with several cars and a few small buildings. The background shows more trees and some residential or commercial buildings. The text "WATERFRONT PARK" is overlaid in the center in a large, white, sans-serif font.

WATERFRONT PARK


A photograph of a coastal promenade. On the left is a building with a brown, textured facade. A paved path with a brick pattern runs along the beach. Several palm trees are planted along the path. People are walking on the path. In the background, the ocean and a distant mountain are visible under a cloudy sky.

COMPLETED
IN
1992

A photograph of a tropical beach promenade. In the foreground, a paved walkway leads towards the ocean. Several people are walking along the path, including a man in a pink and white patterned shirt and a woman in a blue shirt and white skirt. To the left of the path, there are tall palm trees and a grassy area. To the right, the beach and the ocean are visible. The sky is blue with some clouds. Overlaid on the right side of the image is the text 'COST: \$23.7 MILLION' in a large, white, serif font.

**COST:
\$23.7
MILLION**

Kakaako Waterfront Park



Needed repairs



Promenade



Access to trees for maintenance



Lookout





Restroom



Light poles



Overhead lights



Ground lights



Unpermitted
alteration

Backflow preventer

Running water





Broken sprinklers





Water leaks near exposed wires



Trash





Irrigation systems



Extension cords



Fire damage



**REPAIRS
ESTIMATE
OVER \$500,000**